


# EPR dosimetry for actual and suspected overexposures during radiotherapy treatment

F. Trompier<sup>1</sup>, J. Sadlo<sup>2</sup>, J. Michalik<sup>2</sup>, W. Stachowicz<sup>2</sup>, A. Mazal<sup>3</sup>, I. Clairand<sup>1</sup>, J. Rostkowska<sup>4</sup>, W. Bulski<sup>4</sup>, A. Kulakowski<sup>5</sup>, J. Sluszniak<sup>5</sup>, S.Gozdz<sup>5</sup> and A. Wojcik<sup>2,6</sup> <sup>1</sup> IRSN, France, <sup>2</sup>Institute of Nuclear Chemistry and Technology, Warsaw, Poland, <sup>3</sup> Institut Curie, Paris, France, <sup>4</sup> Institute of Oncology, Warsaw, Poland, <sup>5</sup> Holy Cross Cancer Center, Kielce, Poland, <sup>6</sup> Institute of Biology, Swietokrzyska Academy, Kielce, Poland Contact: francois.trompier@irsn.fr

EPR dosimetry was used to estimate the doses on rib bone samples removed from actual and suspected overexposed patient during radiotherapy treatment

### Case n°1: Dose assessment for a radiotherapy accident

The recognized overexposure occurred on February 27th 2001 in the Bialystok Oncology Center, when five breast-cancer patients undergoing radiotherapy received a single, high dose of 8 MeV electrons generated by a Neptun 10p linear accelerator. The ultimate cause of the accident was a defective safety interlock and an obsolete safety system of the Neptun 10p accelerator leading to a large increase of the dose rate. All patients experienced immediate pain and skin reddening, followed by moist desquamation and development of deep necroses by autumn 2001.




Case n°2: investigation for a suspected overexposure

In 2005, a patient developed necrosis in the right axillary region formerly irradiated (9MV photon) during "standard upper mantel fields" therapy for an Hodgkin's disease in 1999. A late effect of an overexposure during the treatment was considered as an plausible hypothesis for the necrosis appearance.

#### Materials and methods


Doses were assessed by the dose addition method on cortical part of rib bone sample. Post irradiation performed using 9 MV electron (IRSN) and 60Co gamma (INCT) for Byalistock accident samples and 60Co gamma (IRSN) for the case n°2. Variation of beam and energy response was taken into account when necessary.




Post-irradiation with 9 MV eat the Institut Curie (France) for Bialystock samples


Dose estimation

#### Dose estimation



\*Correction factor e-/ $\gamma$ : 1.11





## Total dose measured on rib bone by EPR (Gy)


	Patient 3	Patient 4	Patient 5
Total EPR dose (IRSN)	83±7	98±10	75±3
Total EPR dose (INCT)*	95±5	95±6	-
Dose before accident**	25±0.3	39 ±1	5 ±0.3
Accident Dose**	58±7	59±10	70±5


#### Good agreement between EPR results

Differences and uncertainties for dose reconstruction based on EPR data are coming from:

- Accuracy of sample position
- Fast attenuation of electrons
- Accuracy on cumulative dose before accident
- Effect of necrosis on ESR signal


## 3 samples from the rib bone: \$1,\$2 and S3





## Dose results

Sample 1 Sample 2 Sample 3 10.2±1.1 EPR dose (Gy)\* 4.5±0.7  $6.9\pm0.7$ 13.2±0.6 13.7±1.1 7.5 ±0.4 Slope of LR\*\*



- \*in tissue kerma corrected from energy variation \*\*slope for LR in air kerma, 60Co
- Problem for dose reconstruction, no available data to correct measured doses from the loss of EPR signal due to bone remodelling and the influence of necrosis on signal loss and dose sensitivity
- No conclusions on radio-induced origin of the pathology

These two cases show that EPR can provide useful data and that some specific studies on bone dosimetry are neccesary to improve analysis of data

from Accidental overexposure of radiotherapy patients in Bialystok, IAEA, Vienna, 2004